

Finnoff Aviation
185 Bellevue Drive
Boulder, CO 80302
chris@finnoff.com
(303) 444-0552

Aircraft Specifications – Pilatus PC12/45 S/N 114, Reg. N121RF, 1995

Airframe, Engine, and Prop

Airframe Total Time 2375 hours
Engine Total Time 2375 hours
Newly Overhauled Prop. (@ 2300 Hrs.)
Paint: Vestal White wih RBG Stripes – Done March 1998, Updated August 2001

Avionics Options

Honeywell Avionics on Honeywell Protection Plan (HAPP)
Pilot and Copilot 4 Inch EFIS (4 Tube)
Garmin Audio Panel
Dual Xpndrs – King KT70 (Mode S), Terra 250D
Garmin MX200 MFD with Chart View
Garmin GDL 69A Data Uplink
Dual AHRS LCR-92
WX1000 Stormscope
SkyWatch TAS with Separate Indicator
King KGP 560 EGPWS
HF KTR-953
Dual KX-165 (8.33 MHz) Nav/Coms
King KLN 90B GPS
King KRA 405 Radar Altimeter
RS-181VP Weather Radar
2nd GPS-60 (Separate Bus/Antenna)
Kennedy Technologies CellSet
Pilot and Copilot Sennheiser Noise-Cancelling Headsets

Optional Equipment

Supplemental Air Conditioning System
Dual Windshield Upgrade (Larger Heated Area)
Heating System Upgrade
Insulation Upgrade
Steel Brakes – New in June 2007
Cockpit Fire Extinguisher
Recognition Lights
Rotating Whelen Beacons – Top/Bottom
Emergency Power System
Iridium SatPhone 9500 (External Power/Antenna)

Hell Hold Modification:

- Locking
- Light
- Tow Head Stowage
- Ladder
- Hidden Disconnect
- Caution Cones

Tronair Tow Heads (2) and Tow Bar

External Light Switch – Stairway

Deluxe Stairway with Chrome Handrail

Pilot Relief Tube

Landing Gear Squat Timer

Ground Clearance Switch

Cabin Door Heat Cover

Flight Display Systems Entertainments System

- Three 7" Monitors
- Bulkhead 10" Monitor
- Keyboard with Remote Ports/USB Jacks

Five Wireless Sennheiser Head Phones

Lumina DVD

Clarion 6 CD Changer

AI-Audio Switching – XM/CD/DVD/ATC

12V Access Jacks (2)

... And More!

Interior

Executive 6-Seat Interior (6 Cabin, +2 Cockpit, Refurbished in March 2007)

Teal Leather Executive Seats

Club Configuration with Three Stowable Tables

Additional Piece of Aft Carpeting

Other

One Owner Since New

Pilatus Service Center Maintained

No Damage History

On Stevens Trend Monitoring

Photos





